

SITE OBSERVATION FORM: DNV Landslide Risk Assessment
LOCATION: Hayseed-Layton Gully
INSPECTION DATE: (mm/dd/yy) 10/28/05
WEATHER: Cloudy with periods of rain



BGC ENGINEERING INC.
 AN APPLIED EARTH SCIENCES COMPANY

500 - 1045 Howe Street
 Vancouver, BC
 Canada V6Z 2A9

| THICKNESS OF LOOSE MATERIALS | <1 m | 1-2 m | 2-3 m | >3 m |
|---|-------------------------------------|-------|-------|------|
| FENCE LINE | <input checked="" type="checkbox"/> | | | |
| 12 m DOWNSLOPE FROM FENCE LINE AT CREST | <input checked="" type="checkbox"/> | | | |

| SLOPE BELOW FENCE/ RETAINING STRUCTURE | SLOPE = 33° | | |
|---|-------------|--------|---------|
| | CRACKS | SLIDES | EROSION |
| OBSERVATIONS: None slope deformation observed. House is 15-16m from the old gravel pit and over 30m to the crest of the slope | | | |


| TREES BELOW FENCE/ RETAINING STRUCTURE | STRAIGHT | PISTOL-BUTT | LEANING |
|--|----------|-------------|-------------------------------------|
| PERCENT CONIFER: 80% | | | <input checked="" type="checkbox"/> |
| OBSERVATIONS: Some coniferous trees slightly swayed on the south side of the slope below crest. A few deciduous trees and high shrubs are the only vegetation in the old gravel pit/gully. | | | |

| RETAINING STRUCTURES | YES | NO <input checked="" type="checkbox"/> | HEIGHT= n/a |
|-----------------------------|------------|--|-------------|
| TYPE | CONCRETE | TIMBER CRIB | OTHER: |
| DEFORMATION | UNDEFORMED | CRACKED | BULGING |
| OBSERVATIONS: None observed | | | |

| DEFORMATION IN BACKYARD | YES | NO <input checked="" type="checkbox"/> |
|---|-----|--|
| LOCATION: Backyard of 2442 Hayseed Close | | |
| DESCRIPTION: Minor undulation in lawn area. No history of slope movement at this property according to owner. | | |

| POOLS | YES | NO <input checked="" type="checkbox"/> |
|--------------------------------|-----|--|
| DESCRIPTION: Hot tub on patio. | | |

| SEEPAGE/ SPRINGS IN OR BELOW FILL | YES | NO <input checked="" type="checkbox"/> |
|-----------------------------------|-----|--|
| OBSERVATIONS: None observed | | |



HOUSE DISTANCE TO CREST = 30 m

| RECEIVES SURFACE RUNOFF FROM | BACKYARD <input checked="" type="checkbox"/> | 1/2 ROOF | FULL ROOF | FRONT YARD | STREET |
|--|--|----------|-----------|------------|--------|
| OBSERVATIONS: 2442 Hayseed Close may get some street run off in large storm event. | | | | | |

| CONNECTED TO STORM SEWER | YES | NO <input checked="" type="checkbox"/> | UNSURE |
|--|-----|--|--------|
| OWNERS COMMENTS: Owner notes that the house at 2442 Hayseed Close is completely connected to storm sewer. 2 manholes on property, 1 located, 1 not visible. DNV reports that the property is not connected to the storm sewer. | | | |

GENERAL OBSERVATIONS

- Park/gully immediately below 2442 Hayseed Close, 1869 and 1851 Layton properties is an old gravel pit
- Gully at end of gravel pit has been filled with soil and woody debris
- Auger holes were drilled at 2442 Hayseed Close property line and estimated location of crest of main slope (before gravel pit excavation).



Figure 1. Hayseed-Layton Gully - Front of 2442 Hayseed



Figure 2. Hayseed-Layton Gully – View of 2442 Hayseed looking north from south side of gravel pit



Figure 3. Hayseed-Layton Gully – View looking SE along property line of 2442 Hayseed

INSPECTION LOCATION # Hayseed - Layton Gully

Project : DNV Landslide Risk Assessment

Project No. : 0404-002-01

Location : Hayseed - Layton Gully
Drill Method : Dutch Hand Auger
Inspection Date : 28 Oct 05
Logged by : SF/JB
Reviewed by : MJP

| Depth (m) | Lithologic Description | Depth To Water Table | Depth (m) | Lithologic Description | Depth To Water Table |
|-----------|---|----------------------|-----------|---|----------------------|
| | <p>AUGERHOLE: BGC05-2442HAY-LHG-AH01 on Slope Crest FINAL DEPTH OF AUGERHOLE: 0.40 m THICKNESS OF LOOSE MATERIALS: 0.40 m minimum</p> | | | <p>AUGERHOLE: BGC05-2442HAY-LHG-AH02 12 m Downslope FINAL DEPTH OF AUGERHOLE: 0.55 m THICKNESS OF LOOSE MATERIALS: 0.55 m minimum</p> | |
| 0.0 | ORGANICS and SAND (SP) Fine to coarse sand, trace silt, poorly graded, very loose, dark brown, slight odour, moist, homogeneous [TOPSOIL] | | 0.0 | ORGANICS Trace silt and gravel [TOPSOIL] | |
| 0.5 | SAND (SP) Medium to coarse, gravelly, fine to coarse gravel, maximum particle size = 35 mm, sub-rounded, poorly graded, very loose, light yellow brown, no odour, moist, homogeneous, mostly coarse sand [FILL or COLLUVIUM] 0.40 m :EOH - Refusal on cobble Hole collapsing. | | 0.5 | SAND (SW) and GRAVEL (GW) Fine to coarse sand, fine to coarse gravel, some silt, trace cobbles, well graded, very loose, maximum particle size = 200 mm, sub-rounded, brown, no odour, moist, homogeneous, roots and rootlets [FILL] SAND (SW) and GRAVEL (GW) Fine to coarse sand, fine to coarse gravel, trace silt and trace cobbles, well graded, very loose, maximum particle size = 200 mm, sub-rounded, brown, no odour, moist, homogeneous [FILL] 0.55 m: EOH - Refusal as hole is collapsing | |
| 1.0 | | | 1.0 | | |
| 1.5 | | | 1.5 | | |
| 2.0 | | | 2.0 | | |
| 2.5 | | | 2.5 | | |
| 3.0 | | | 3.0 | | |

BGC05-2442HAY-LHG-AH01

SITE OBSERVATION FORM: DNV Landslide Risk Assessment
LOCATION: 2448 Hayseed Close
INSPECTION DATE: (mm/dd/yy) 10/28/05
WEATHER: Cloudy with periods of rain



BGC ENGINEERING INC.
 AN APPLIED EARTH SCIENCES COMPANY

500 - 1045 Howe Street
 Vancouver, BC
 Canada V6Z 2A9

| THICKNESS OF LOOSE MATERIALS | <1 m | 1-2 m | 2-3 m | >3 m |
|---------------------------------|------|-------------------------------------|-------------------------------------|------|
| FENCE LINE | | <input checked="" type="checkbox"/> | | |
| 12 m DOWNSLOPE FROM SLOPE CREST | | | <input checked="" type="checkbox"/> | |

| SLOPE BELOW FENCE/ RETAINING STRUCTURE | SLOPE = 35° | | |
|--|-------------|--------|-------------------------------------|
| | CRACKS | SLIDES | EROSION |
| OBSERVATIONS: Minor slope erosion observed | | | <input checked="" type="checkbox"/> |


| TREES BELOW FENCE/ RETAINING STRUCTURE | STRAIGHT | PISTOL-BUTT | LEANING |
|--|----------|-------------------------------------|---------|
| PERCENT CONIFER: 90% | | <input checked="" type="checkbox"/> | |
| OBSERVATIONS: Slight pistol butting on approximately 50% of trees. | | | |

| RETAINING STRUCTURES | YES <input checked="" type="checkbox"/> | NO | HEIGHT= 0.8 m |
|---|---|-------------|---------------------------|
| TYPE | BLOCKS CONCRETE | TIMBER CRIB | OTHER: Landscape tie crib |
| DEFORMATION | UNDEFORMED | SETTLED | BULGING |
| OBSERVATIONS: No evidence of deformation. | | | |

| DEFORMATION IN BACKYARD | YES <input checked="" type="checkbox"/> | NO |
|---|---|----|
| LOCATION: Backyard | | |
| DESCRIPTION: Backyard dips towards slope. | | |

| POOLS | YES <input checked="" type="checkbox"/> | NO |
|-----------------------|---|----|
| DESCRIPTION: Hot tub. | | |

| SEEPAGE/ SPRINGS IN OR BELOW FILL | YES | NO <input checked="" type="checkbox"/> |
|-----------------------------------|-----|--|
| OBSERVATIONS: None observed. | | |



HOUSE DISTANCE TO CREST = 7.5 m

| RECEIVES SURFACE RUNOFF FROM | BACKYARD <input checked="" type="checkbox"/> | 1/2 ROOF <input checked="" type="checkbox"/> | FULL ROOF | FRONT YARD | STREET |
|---|--|--|-----------|------------|--------|
| OBSERVATIONS: Backyard downspouts drain on to ground. | | | | | |

| CONNECTED TO STORM SEWER | YES | NO <input checked="" type="checkbox"/> | UNSURE |
|---|-----|--|--------|
| OWNERS COMMENTS: DNV reports that this property is not connected to the storm sewer system. | | | |

- GENERAL OBSERVATIONS**
- Old septic system exists in backyard
 - Retaining wall consists of 2 steps with a walkway between
 - Thickness of loose materials at crest are estimated since auger hole 1 refused at 0.8m in coarse gravel that was imported for the old septic system



Figure 1. 2448 Hayseed Close – Front of the house



Figure 2. 2448 Hayseed Close – Timber crib retaining structure



Figure 3. 2448 Hayseed Close – View down-slope from crest

INSPECTION LOCATION # 2448 Hayseed

Project : DNV Landslide Risk Assessment

Project No. : 0404-002-01

Location : 2448 Hayseed
Drill Method : Dutch Hand Auger
Inspection Date : 28 Oct 05
Logged by : MB/ES
Reviewed by : MJP

| Depth (m) | Lithologic Description | Depth To Water Table | Depth (m) | Lithologic Description | Depth To Water Table |
|-----------|---|----------------------|-----------|---|----------------------|
| | <p>AUGERHOLE: BGC05-2448HAY-AH01 on Slope Crest FINAL DEPTH OF AUGERHOLE: 0.80 m THICKNESS OF LOOSE MATERIALS: 0.80 m minimum</p> | | | <p>AUGERHOLE: BGC05-2448HAY-AH02 12 m Downslope FINAL DEPTH OF AUGERHOLE: 2.00 m THICKNESS OF LOOSE MATERIALS: 2.00 m minimum</p> | |
| 0.0 | <p>SAND (SM) Silty, some fine to coarse gravel, some cobbles, well graded, loose, maximum particle size = 80 mm, sub-rounded, brown to dark brown, no odour, moist, homogeneous, no cement [FILL]</p> | | 0.0 | <p>SAND (SM) Fine to medium sand, silty, trace fine gravel, loose, poorly graded, maximum particle size = 4 mm, dark brown, no odour, moist, homogeneous, no cementation, roots [TOPSOIL]</p> | |
| 0.5 | <p>0.50 - 0.60 m: High gravel content, SAND (SM) and GRAVEL (GP), coarse gravel</p> | | 0.5 | <p>SAND (SW) Fine to coarse sand, some fine to coarse gravel, trace silt, trace cobbles, well graded, loose, maximum particle size = 80 mm, sub-rounded to sub-angular, brown, no odour, moist, homogeneous, no cementation [FILL]</p> | |
| 1.0 | <p>4 inch ceramic pipe encountered at 0.6 m, occupant confirms pipe is part of an old septic tank system. 0.80 m: EOH - Refusal on ceramic pipe and gravel Three holes attempted along crest.</p> | | 1.0 | | |
| 1.5 | | | 1.5 | | |
| 2.0 | | | 2.0 | <p>SAND (SP) Mostly medium sand, trace gravel, trace silt, some gravel sized sand clasts, poorly graded, loose, maximum particle size = 5 mm, sub angular, light brown, no odour, moist, homogeneous, no cementation, easily broken on handling [FILL/ COLLUVIUM] 2.00 m: EOH - Refusal on cobbles at 2.00 m No watertable encountered</p> | |
| 2.5 | | | 2.5 | | |
| 3.0 | | | 3.0 | | |

BGC05-2448HAY-AH01

| | |
|------------------------------------|--------------------------------------|
| SITE OBSERVATION FORM: | DNV Landslide Risk Assessment |
| LOCATION: | 2454 Hayseed Close |
| INSPECTION DATE: (mm/dd/yy) | 10/27/05 |
| WEATHER: | Cloudy, rained previous night |



BGC ENGINEERING INC.
AN APPLIED EARTH SCIENCES COMPANY

500 - 1045 Howe Street
Vancouver, BC
Canada V6Z 2A9


| | | | | |
|--|------|-------------------------------------|-------------------------------------|------|
| THICKNESS OF LOOSE MATERIALS | <1 m | 1-2 m | 2-3 m | >3 m |
| FENCE LINE | | | <input checked="" type="checkbox"/> | |
| 15 m DOWNSLOPE FROM SLOPE CREST | | <input checked="" type="checkbox"/> | | |

| | | | |
|---|--------------------|---------------|-------------------------------------|
| SLOPE BELOW FENCE/ RETAINING STRUCTURE | SLOPE = 33° | | |
| | CRACKS | SLIDES | EROSION |
| | | | <input checked="" type="checkbox"/> |
| OBSERVATIONS: Minor slope erosion observed | | | |

| | | | |
|--|-----------------|-------------------------------------|----------------|
| TREES BELOW FENCE/ RETAINING STRUCTURE | STRAIGHT | PISTOL-BUTT | LEANING |
| PERCENT CONIFER: | 100% | <input checked="" type="checkbox"/> | |
| OBSERVATIONS: Slope is heavily vegetated by ivy and ferns | | | |

| | | | |
|---|--|-----------------|----------------------------------|
| RETAINING STRUCTURES | YES <input checked="" type="checkbox"/> | NO | HEIGHT= 3.3 m |
| TYPE | BLOCKS | CONCRETE | TIMBER CRIB |
| | | | OTHER: Landscape tie crib |
| DEFORMATION | UNDEFORMED | CRACKED | SETTLED |
| | | | BULGING |
| OBSERVATIONS: Retaining wall consists of 2 steps; both are 1.5m in height. No evidence of deformation. | | | |

| | | |
|--|--|-----------|
| DEFORMATION IN BACKYARD | YES <input checked="" type="checkbox"/> | NO |
| LOCATION: Backyard | | |
| DESCRIPTION: Backyard dips towards slope. Slight cracks in concrete patio 2 m from house. | | |



HOUSE DISTANCE TO CREST = 9.7 m

| | | |
|---------------------|------------|---|
| POOLS | YES | NO <input checked="" type="checkbox"/> |
| DESCRIPTION: | | |

| | | |
|--|------------|---|
| SEEPAGE/ SPRINGS IN OR BELOW FILL | YES | NO <input checked="" type="checkbox"/> |
| OBSERVATIONS: None observed | | |

| | | | | | |
|---|-------------------------------------|-------------------------------------|------------------|-------------------|---------------|
| RECEIVES SURFACE RUNOFF FROM | BACKYARD | ½ ROOF | FULL ROOF | FRONT YARD | STREET |
| | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | | | |
| OBSERVATIONS: Front yard dips towards street | | | | | |

| | | | |
|--|------------|-----------|---|
| CONNECTED TO STORM SEWER | YES | NO | UNSURE <input checked="" type="checkbox"/> |
| OWNERS COMMENTS: Occupant believes that house is connected to storm sewer. DNV reports that this property is not connected to the storm sewer system. | | | |

| |
|---|
| GENERAL OBSERVATIONS |
| <ul style="list-style-type: none"> Backyard dips towards slope |



Figure 1. 2454 Hayseed Close – Front of the house



Figure 2. 2454 Hayseed Close – Timber crib retaining wall



Figure 3. 2454 Hayseed Close – View down-slope from south side of property looking NW



Figure 4. 2454 Hayseed Close – Lawn in the backyard dips towards the slope

INSPECTION LOCATION # 2454 Hayseed

Project : DNV Landslide Risk Assessment

Project No. : 0404-002-01

Location : 2454 Hayseed
Drill Method : Dutch Hand Auger
Inspection Date : 28 Oct 05
Logged by : MB/ES
Reviewed by : MJP

| Depth (m) | Lithologic Description | Depth To Water Table | Depth (m) | Lithologic Description | Depth To Water Table |
|-----------|---|----------------------|-----------|--|----------------------|
| | <p>AUGERHOLE: BGC05-2454HAY-AH01 0.5 m South of Slope Crest FINAL DEPTH OF AUGERHOLE: 2.70 m THICKNESS OF LOOSE MATERIALS: 2.70 m minimum</p> | | | <p>AUGERHOLE: BGC05-2454HAY-AH02 15 m Downslope FINAL DEPTH OF AUGERHOLE: 1.20 m THICKNESS OF LOOSE MATERIALS: 1.20 m minimum</p> | |
| 0.0 | <p>SAND (SM) Fine to medium sand, silty, trace fine gravel, poorly graded, loose, dark brown, no odour, moist, homogeneous, no cementation, rootlets [TOPSOIL]</p> | | 0.0 | <p>SAND (SM) Silty sand, trace fine gravel, poorly graded, loose, max particle size = 3 mm, dark brown, no odour, moist, homogeneous, no cementation, some rootlets [TOPSOIL]</p> | |
| 0.5 | <p>SAND (SW) Fine to coarse, trace silt, trace fine to medium gravel, well graded sand, loose, maximum particle size = 20 mm, sub rounded, grey peppered appearance, no odour, moist, homogeneous, no cementation, trace rootlets [FILL]</p> | | 0.5 | <p>SAND (SM) Silty sand, some cobbles, trace gravel, poorly graded, loose, max particle size = 100 mm, brown, no odour, dry, homogeneous, no cementation, trace rootlets [FILL/ COLLUVIUM]</p> | |
| 1.0 | <p>SAND (SP) Fine to medium sand, trace silt, trace fine to medium gravel, gravel sized clasts of fine sand and silt, poorly graded, loose, max particle size = 13 mm, light brown, no odour, moist, homogeneous, no cementation, trace rootlets [FILL]</p> | | 1.0 | | |
| 1.5 | <p>1.50 m - Garbage and charcoal SAND (SP) Mostly fine to medium sand, some silt, trace fine to coarse gravel, poorly graded, loose, max particle size = 40 mm, sub rounded, brown, no odour, moist, homogeneous, no cementation, trace roots, charcoal [FILL]</p> | | 1.5 | <p>1.20 m: EOH - Refusal on cobbles No groundwater encountered</p> | |
| 2.0 | | | 2.0 | | |
| 2.5 | | | 2.5 | | |
| 3.0 | <p>2.70 m: EOH - Refusal of auger on cobbles</p> | | 3.0 | | |

BGC05-2454HAY-AH01

| | |
|------------------------------------|--------------------------------------|
| SITE OBSERVATION FORM: | DNV Landslide Risk Assessment |
| LOCATION: | 2462 Hayseed Close |
| INSPECTION DATE: (mm/dd/yy) | 10/28/05 |
| WEATHER: | Cloudy, rained previous night |



BGC ENGINEERING INC.
AN APPLIED EARTH SCIENCES COMPANY

500 - 1045 Howe Street
Vancouver, BC
Canada V6Z 2A9


| | | | | |
|--|------|-------------------------------------|-------|------|
| THICKNESS OF LOOSE MATERIALS | <1 m | 1-2 m | 2-3 m | >3 m |
| FENCE LINE | | <input checked="" type="checkbox"/> | | |
| 12 m DOWNSLOPE FROM SLOPE CREST | | <input checked="" type="checkbox"/> | | |

| | | | |
|--|--------------------|---------------|-------------------------------------|
| SLOPE BELOW FENCE/ RETAINING STRUCTURE | SLOPE = 40° | | |
| | CRACKS | SLIDES | EROSION |
| OBSERVATIONS: Minor slope erosion observed. | | | <input checked="" type="checkbox"/> |

| | | | |
|---|-----------------|--------------------|-------------------------------------|
| TREES BELOW FENCE/ RETAINING STRUCTURE | STRAIGHT | PISTOL-BUTT | LEANING |
| PERCENT CONIFER: | <50% | | <input checked="" type="checkbox"/> |
| OBSERVATIONS: Minor pistol butting on some trees. Heavily vegetated with shrubs. | | | |

| | | | |
|--|--|-------------------------------------|-------------------------------------|
| RETAINING STRUCTURES | YES <input checked="" type="checkbox"/> | NO | HEIGHT= 0.5-0.6m |
| TYPE | BLOCKS | CONCRETE | TIMBER CRIB |
| DEFORMATION | UNDEFORMED | CRACKED | SETTLED |
| | | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| OBSERVATIONS: 3 terraced retaining walls. All are cracking, leaning or are detached and falling over. | | | |

| | | |
|---|--|-----------|
| DEFORMATION IN BACKYARD | YES <input checked="" type="checkbox"/> | NO |
| LOCATION: Backyard | | |
| DESCRIPTION: Undulating ground, some minor settlement. Owner notes that nothing has changed in last 7-8 years. | | |



| | | |
|---------------------------|------------|---|
| POOLS | YES | NO <input checked="" type="checkbox"/> |
| DESCRIPTION: None. | | |

| | | |
|--|------------|---|
| SEEPAGE/ SPRINGS IN OR BELOW FILL | YES | NO <input checked="" type="checkbox"/> |
| OBSERVATIONS: None observed. | | |

HOUSE DISTANCE TO CREST = 10.6 m

| | | | | | |
|--|-------------------------------------|-------------------------------------|-------------------------------------|-------------------|---------------|
| RECEIVES SURFACE RUNOFF FROM | BACKYARD | ½ ROOF | FULL ROOF | FRONT YARD | STREET |
| | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | | |
| OBSERVATIONS: Owner noted that gravel drain in driveway drains toward street. | | | | | |

| | | | |
|---|------------|---|---------------|
| CONNECTED TO STORM SEWER | YES | NO <input checked="" type="checkbox"/> | UNSURE |
| OWNERS COMMENTS: No drains observed at base of lowest retaining wall. DNV reports that this property is not connected to the storm sewer system. | | | |

| |
|---|
| GENERAL OBSERVATIONS |
| <ul style="list-style-type: none"> House distance to landscaped crest/ retaining wall is 10.6 m; House distance to estimated natural crest of slope is 4 m. Boulders and cement from lower retaining wall fallen down slope. Surface erosion below north part of retaining wall. |



Figure 1. 2462 Hayseed Close - Front of the house



Figure 2. 2462 Hayseed Close – View of backyard looking north

INSPECTION LOCATION # 2462 Hayseed

Project : DNV Landslide Risk Assessment

Project No. : 0404-002-01

Location : 2462 Hayseed
Drill Method : Dutch Hand Auger
Inspection Date : 28 Oct 05
Logged by : SF/JB
Reviewed by : MJP

| Depth (m) | Lithologic Description | Depth To Water Table | Depth (m) | Lithologic Description | Depth To Water Table |
|-----------|---|----------------------|-----------|--|----------------------|
| | <p>AUGERHOLE: BGC05-2462HAY-AH01 on Slope Crest FINAL DEPTH OF AUGERHOLE: 1.25 m THICKNESS OF LOOSE MATERIALS: 1.25 m minimum</p> | | | <p>AUGERHOLE: BGC05-2462HAY-AH02 12 m Downslope FINAL DEPTH OF AUGERHOLE: 1.25 m THICKNESS OF LOOSE MATERIALS: 1.25 m minimum</p> | |
| 0.0 | ORGANICS Very loose, moist, homogeneous | | 0.0 | ORGANICS | |
| 0.5 | GRAVEL (GP) and SAND (SP) Fine to coarse gravel, medium to coarse sand, trace silt, poorly graded, loose, maximum particle size = 50 mm, sub-rounded, brown, no odour, moist, homogeneous, no cement, rootlets [FILL] | | 0.5 | GRAVEL (GW) and SAND (SW) Fine to coarse gravel, medium to coarse sand, well graded, loose, maximum particle size = 55 mm, light brown, no odour, moist, homogeneous, no cementation, rootlets [COLLUVIUM] | |
| 1.0 | 0.90 m - grading to light brown by 1.20 m | | 1.0 | | |
| 1.5 | 1.25 m: EOH - Refusal of auger on coarse gravel | | 1.5 | 1.25 m: EOH - Refusal on coarse gravel at 1.25 m Attempted another hole 6 m farther downslope - refusal on gravel at 0.50 m | |
| 2.0 | | | 2.0 | | |
| 2.5 | | | 2.5 | | |
| 3.0 | | | 3.0 | | |

BGC05-2462HAY-AH01

BGC ENGINEERING INC.
AN APPLIED EARTH SCIENCES COMPANY
Vancouver, BC Phone: (604) 684 5900

Client: District of North Vancouver

| | |
|------------------------------------|--------------------------------------|
| SITE OBSERVATION FORM: | DNV Landslide Risk Assessment |
| LOCATION: | 2468 Hayseed Close |
| INSPECTION DATE: (mm/dd/yy) | 10/27/05 |
| WEATHER: | Cloudy, rained previous night |



BGC ENGINEERING INC.
AN APPLIED EARTH SCIENCES COMPANY

500 - 1045 Howe Street
Vancouver, BC
Canada V6Z 2A9

| THICKNESS OF LOOSE MATERIALS | <1 m | 1-2 m | 2-3 m | >3 m |
|--------------------------------|------|-------------------------------------|-------|------|
| FENCE LINE | | <input checked="" type="checkbox"/> | | |
| 6 m DOWNSLOPE FROM SLOPE CREST | | <input checked="" type="checkbox"/> | | |

| | | | |
|---|-----------------------|---------------|----------------|
| SLOPE BELOW FENCE/ RETAINING STRUCTURE | SLOPE = 34-35° | | |
| | CRACKS | SLIDES | EROSION |
| OBSERVATIONS: None observed. | | | |


| | | | |
|---|-----------------|-------------------------------------|----------------|
| TREES BELOW FENCE/ RETAINING STRUCTURE | STRAIGHT | PISTOL-BUTT | LEANING |
| PERCENT CONIFER: | 50% | <input checked="" type="checkbox"/> | |
| OBSERVATIONS: Some swayed trees, mostly straight, many removed | | | |

| | | | |
|-------------------------------------|-------------------|---|--------------------|
| RETAINING STRUCTURES | YES | NO <input checked="" type="checkbox"/> | HEIGHT= n/a |
| TYPE | BLOCKS | CONCRETE | TIMBER CRIB |
| DEFORMATION | UNDEFORMED | CRACKED | SETTLED |
| OBSERVATIONS: None observed. | | | |

| | | |
|---|------------|---|
| DEFORMATION IN BACKYARD | YES | NO <input checked="" type="checkbox"/> |
| LOCATION: | | |
| DESCRIPTION: No backyard. Property is occupied entirely by house and elevated sundeck. | | |

| | | |
|--|------------|---|
| POOLS | YES | NO <input checked="" type="checkbox"/> |
| DESCRIPTION: Small garden pond exists in front yard, no visible cracks. | | |

| | | |
|--|------------|---|
| SEEPAGE/ SPRINGS IN OR BELOW FILL | YES | NO <input checked="" type="checkbox"/> |
| OBSERVATIONS: None observed. | | |



HOUSE DISTANCE TO CREST = 0 m

| | | | | | |
|---|-------------------------------------|-------------------------------------|-------------------------------------|-------------------|---------------|
| RECEIVES SURFACE RUNOFF FROM | BACKYARD | 1/2 ROOF | FULL ROOF | FRONT YARD | STREET |
| | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | | |
| OBSERVATIONS: Front yard slopes towards road ~ 2m vertical elevation change. | | | | | |

| | | | |
|--|------------|---|---------------|
| CONNECTED TO STORM SEWER | YES | NO <input checked="" type="checkbox"/> | UNSURE |
| OWNERS COMMENTS: DNV reports that this property is not connected to the storm sewer system. | | | |

| |
|--|
| GENERAL OBSERVATIONS |
| <ul style="list-style-type: none"> House built on crest, wood deck overhangs crest of slope. Two drainage pipes collect water off the north end of the house and drain below the sundeck Thicknesses of loose materials are estimated since auger holes 1 and 2 reached maximum depths of 0.75m and 0.95m respectively. Both holes refused on gravels in loose materials. |



Figure 1. 2468 Hayseed Close – Front of the house



Figure 2. 2468 Hayseed Close - Back fence line with drain pipe in the foreground



Figure 3. 2468 Hayseed Close – Looking NE along fence line

INSPECTION LOCATION # 2468 Hayseed

Project : DNV Landslide Risk Assessment

Project No. : 0404-002-01

Location : 2468 Hayseed
Drill Method : Dutch Hand Auger
Inspection Date : 28 Oct 05
Logged by : SF/JB
Reviewed by : MJP

| Depth (m) | Lithologic Description | Depth To Water Table | Depth (m) | Lithologic Description | Depth To Water Table |
|-----------|---|----------------------|-----------|---|----------------------|
| | <p>AUGERHOLE: BGC05-2468HAY-AH01 on Slope Crest FINAL DEPTH OF AUGERHOLE: 0.75 m THICKNESS OF LOOSE MATERIALS: 0.75 m minimum</p> | | | <p>AUGERHOLE: BGC05-2468HAY-AH02 6 m Downslope FINAL DEPTH OF AUGERHOLE: 0.95 m THICKNESS OF LOOSE MATERIALS: 0.95 m minimum</p> | |
| 0.0 | <p>SAND (SP) Fine to coarse, some fine to coarse gravel, trace silt, poorly graded, loose, maximum particle size = 50 mm, sub-rounded, brown, moist, homogeneous, no organics [FILL]</p> | | 0.0 | <p>SAND (SP) Fine to coarse sand, mostly medium to coarse, some fine to coarse gravel, trace silt, loose, maximum particle size = 50 mm, sub-rounded, brown, moist, homogeneous, some orange brown stained clasts, gravel content coarsening with depth [FILL]</p> | |
| 0.5 | | | 0.5 | <p>0.65 m: Organic layer/lense 0.75 m: Loose, slightly orange brown</p> | |
| 1.0 | <p>0.75 m: EOH - Refusal of auger on gravel</p> | | 1.0 | <p>0.95 m: Trace charcoal clasts 0.95 m: EOH - Refusal on gravels at 0.95 m Attempted second hole 1.5 m downslope, cobbles found in top 0.20 m</p> | |
| 1.5 | | | 1.5 | | |
| 2.0 | | | 2.0 | | |
| 2.5 | | | 2.5 | | |
| 3.0 | | | 3.0 | | |

BGC05-2468HAY-AH01

SITE OBSERVATION FORM: DNV Landslide Risk Assessment
LOCATION: 2474 Hayseed Close
INSPECTION DATE: (mm/dd/yy) 10/27/05
WEATHER: Sunny, rained previous night



BGC ENGINEERING INC.
 AN APPLIED EARTH SCIENCES COMPANY

500 - 1045 Howe Street
 Vancouver, BC
 Canada V6Z 2A9


| THICKNESS OF LOOSE MATERIALS | <1 m | 1-2 m | 2-3 m | >3 m |
|---------------------------------|-------------------------------------|-------------------------------------|-------|------|
| FENCE LINE | | <input checked="" type="checkbox"/> | | |
| 10 m DOWNSLOPE FROM SLOPE CREST | <input checked="" type="checkbox"/> | | | |

| SLOPE BELOW FENCE/ RETAINING STRUCTURE | SLOPE = 33° | | |
|---|-------------|--------|-------------------------------------|
| | CRACKS | SLIDES | EROSION |
| OBSERVATIONS: Some erosion observed ~ 10m below deck. | | | <input checked="" type="checkbox"/> |

| TREES BELOW FENCE/ RETAINING STRUCTURE | STRAIGHT | PISTOL-BUTT | LEANING |
|--|-------------------------------------|-------------|---------|
| PERCENT CONIFER: 90% | <input checked="" type="checkbox"/> | | |
| OBSERVATIONS: Many fallen trees along slope. | | | |

| RETAINING STRUCTURES | YES <input checked="" type="checkbox"/> | NO | HEIGHT= 0.3-0.4m |
|---|--|-------------|---|
| TYPE | CONCRETE <input checked="" type="checkbox"/> | TIMBER CRIB | OTHER: Plywood and stumps <input checked="" type="checkbox"/> |
| DEFORMATION | UNDEFORMED | CRACKED | BULGING <input checked="" type="checkbox"/> |
| OBSERVATIONS: Concrete wall at crest of slope is tilted. In addition to concrete wall, soil is also held in places by plywood propped against stumps. | | | |

| DEFORMATION IN BACKYARD | YES | NO <input checked="" type="checkbox"/> |
|-----------------------------|-----|--|
| LOCATION: | | |
| DESCRIPTION: None observed. | | |



| POOLS | YES | NO <input checked="" type="checkbox"/> |
|-------------------|-----|--|
| DESCRIPTION: None | | |

| SEEPAGE/ SPRINGS IN OR BELOW FILL | YES <input checked="" type="checkbox"/> | NO |
|--|---|----|
| OBSERVATIONS: Evidence of seepage channels ~ 10m below deck. | | |

HOUSE DISTANCE TO CREST = 2.3 m

| RECEIVES SURFACE RUNOFF FROM | BACKYARD <input checked="" type="checkbox"/> | 1/2 ROOF <input checked="" type="checkbox"/> | FULL ROOF | FRONT YARD | STREET |
|---|--|--|-----------|------------|--------|
| OBSERVATIONS: Uncertain if slope receives surface run off from full roof. Front yard dips towards street. | | | | | |

| CONNECTED TO STORM SEWER | YES <input checked="" type="checkbox"/> | NO | UNSURE |
|---|---|----|--------|
| OWNERS COMMENTS: DNV reports that this property is connected to the storm sewer system. | | | |

GENERAL OBSERVATIONS

- Sundeck support posts being replaced (evidence of work in progress).
- Patio/deck built at crest of slope.
- Slope thickly vegetated; fallen trees observed.



Figure 1. 2474 Hayseed Close – Front of the house



Figure 2. 2474 Hayseed Close – Tilted concrete retaining structure



Figure 3. 2474 Hayseed Close – View from crest looking north down-slope



Figure 4. 2474 Hayseed Close – In-progress renovation of deck supports

INSPECTION LOCATION # 2474 Hayseed

Project : DNV Landslide Risk Assessment

Project No. : 0404-002-01

Location : 2474 Hayseed
Drill Method : Dutch Hand Auger
Inspection Date : 27 Oct 05
Logged by : MB/ES
Reviewed by : MJP

| Depth (m) | Lithologic Description | Depth To Water Table | Depth (m) | Lithologic Description | Depth To Water Table |
|-----------|---|----------------------|-----------|---|----------------------|
| | <p>AUGERHOLE: BGC05-2474HAY-AH01 on Slope Crest FINAL DEPTH OF AUGERHOLE: 1.10 m THICKNESS OF LOOSE MATERIALS: 1.10 m minimum</p> | | | <p>AUGERHOLE: BGC05-2474HAY-AH02 10 m Downslope FINAL DEPTH OF AUGERHOLE: 0.70 m THICKNESS OF LOOSE MATERIALS: 0.70 m minimum</p> | |
| 0.0 | <p>SAND (SM) Silty, trace fine to medium gravel, poorly graded, loose, max particle size = 8 mm, sub rounded, dark brown, no odour, moist, homogeneous, no cementation, trace roots [TOPSOIL]</p> | | 0.0 | <p>SAND (SM) Fine to coarse sand, silty, poorly graded, loose, dark brown, no odour, moist, homogeneous, no cementation, trace rootlets [TOPSOIL]</p> | |
| 0.5 | <p>SAND (SM) Fine to medium sand, silty, some fine to medium gravel, some cobbles, some gravel sized silt clasts, poorly graded, loose, maximum particle size = 20 mm, sub-rounded, brown, no odour, moist, homogeneous, trace roots, no cementation [FILL]</p> | | 0.5 | <p>SAND (SP) Fine to medium sand, mostly medium to coarse, some fine to coarse gravel, some silt, some cobbles, loose, maximum particle size = 50 mm, sub-rounded, brown, no odour, moist, homogeneous, no cementation [FILL]</p> | |
| 1.0 | | | 1.0 | <p>0.70 m: EOH- Refusal on cobbles. No groundwater encountered</p> | |
| 1.5 | <p>1.10 m: EOH - Refusal on gravels/cobbles. Five holes attempted at crest. No groundwater encountered</p> | | 1.5 | | |
| 2.0 | | | 2.0 | | |
| 2.5 | | | 2.5 | | |
| 3.0 | | | 3.0 | | |

BGC05-2474HAY-AH01

| | |
|------------------------------------|--------------------------------------|
| SITE OBSERVATION FORM: | DNV Landslide Risk Assessment |
| LOCATION: | 2480 Hayseed Close |
| OCCUPANTS: | Cas Bohlken |
| INSPECTION DATE: (mm/dd/yy) | 10/27/05 |
| WEATHER: | Sunny, rained previous 2 days |



BGC ENGINEERING INC.
AN APPLIED EARTH SCIENCES COMPANY

500 - 1045 Howe Street
Vancouver, BC
Canada V6Z 2A9

| THICKNESS OF LOOSE MATERIALS | <1 m | 1-2 m | 2-3 m | >3 m |
|---------------------------------|-------------------------------------|-------------------------------------|-------|------|
| FENCE LINE | | <input checked="" type="checkbox"/> | | |
| 10 m DOWNSLOPE FROM SLOPE CREST | <input checked="" type="checkbox"/> | | | |

| | | | |
|---|--------------------|---------------|-------------------------------------|
| SLOPE BELOW FENCE/ RETAINING STRUCTURE | SLOPE = 33° | | |
| | CRACKS | SLIDES | EROSION |
| | | | <input checked="" type="checkbox"/> |
| OBSERVATIONS: Minor erosion at the base of the retaining wall; slope is ravelling; prunings and compost present. | | | |


| | | | |
|---|-------------------------------------|--------------------|----------------|
| TREES BELOW FENCE/ RETAINING STRUCTURE | STRAIGHT | PISTOL-BUTT | LEANING |
| PERCENT CONIFER: 90% | <input checked="" type="checkbox"/> | | |
| OBSERVATIONS: Trees are swayed in the downslope direction. | | | |

| | | | |
|--|--|-----------------|-------------------------------------|
| RETAINING STRUCTURES | YES <input checked="" type="checkbox"/> | NO | HEIGHT= 6.4 m |
| TYPE | BLOCKS | CONCRETE | TIMBER CRIB |
| | | | <input checked="" type="checkbox"/> |
| DEFORMATION | UNDEFORMED | CRACKED | SETTLED |
| | | | BULGING |
| | | | <input checked="" type="checkbox"/> |
| OBSERVATIONS: Slight deformation, appears that the deformation may be bulging. No consistent or persistent bulge. Made up of 6" x 8" railway ties put in place by owner after 1979 event. | | | |

| | | |
|--|--|-----------|
| DEFORMATION IN BACKYARD | YES <input checked="" type="checkbox"/> | NO |
| LOCATION: Lawn area between deck and edge of retaining wall. | | |
| DESCRIPTION: Settlement or slumping (max. 10 cm) causing the lawn to be wavy. | | |

| | | |
|--------------------------|------------|---|
| POOLS | YES | NO <input checked="" type="checkbox"/> |
| DESCRIPTION: None | | |

| | | |
|--|------------|---|
| SEEPAGE/ SPRINGS IN OR BELOW FILL | YES | NO <input checked="" type="checkbox"/> |
| OBSERVATIONS: None observed. | | |



HOUSE DISTANCE TO CREST = 5.4 m

| | | | | | |
|---|-------------------------------------|-------------------------------------|-------------------------------------|-------------------|---------------|
| RECEIVES SURFACE RUNOFF FROM | BACKYARD | ½ ROOF | FULL ROOF | FRONT YARD | STREET |
| | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | | |
| OBSERVATIONS: Front yard dips toward street. | | | | | |

| | | | |
|--|------------|---|---------------|
| CONNECTED TO STORM SEWER | YES | NO <input checked="" type="checkbox"/> | UNSURE |
| OWNERS COMMENTS: DNV reports that this property is not connected to the storm sewer system. | | | |

| |
|--|
| GENERAL OBSERVATIONS |
| <ul style="list-style-type: none"> House is 5.4 m from crest of retaining wall and 2.5-3 m from the original crest line as estimated by neighbours yards. Drainage pipe runs from roof, through backyard fill and out near the base of the retaining wall, but not all roof drains are connected Chicken wire holding gravely material behind retaining walls between timbers in upper sections of wall |



Figure 1. 2480 Hayseed Close – View of front of house



Figure 2. 2480 Hayseed Close – View looking NE along crest



Figure 3. 2480 Hayseed Close – Timber crib retaining wall with protruding drainage pipe



Figure 4. 2480 Hayseed Close – Timber crib retaining wall

INSPECTION LOCATION # 2480 Hayseed

Project : DNV Landslide Risk Assessment

Project No. : 0404-002-01

Location : 2480 Hayseed
Drill Method : Dutch Hand Auger
Inspection Date : 27 Oct 05
Logged by : SF/JB
Reviewed by : MJP

| Depth (m) | Lithologic Description | Depth To Water Table | Depth (m) | Lithologic Description | Depth To Water Table |
|-----------|--|----------------------|-----------|--|----------------------|
| | <p>AUGERHOLE: BGC05-2480HAY-AH01 on Original Slope Crest FINAL DEPTH OF AUGERHOLE: 0.65 m THICKNESS OF LOOSE MATERIALS: 0.65 m minimum (estimate 1-2 m)</p> | | | <p>AUGERHOLE: BGC05-2480HAY-AH02 10 m Downslope FINAL DEPTH OF AUGERHOLE: 0.45 m THICKNESS OF LOOSE MATERIALS: 0.45 m minimum</p> | |
| 0.0 | <p>SILT (ML) Sandy, fine to coarse, low plastic, very loose, dark brown, moist, organic odour [TOPSOIL]</p> | | 0.0 | <p>ORGANICS Silty, very loose, dry, dark brown</p> | |
| 0.5 | <p>SAND (SW) Some silt, some fine to coarse gravels, trace cobbles, well graded, very loose, max particle size = 140 mm, sub rounded, dark brown, organic odour, moist, homogeneous, no cementation, rootlets and other organics, pieces of geotextile and polyurethane [FILL]</p> | | 0.5 | <p>SAND (SP) Medium to coarse sand, some fine to coarse gravel, trace silt, very loose, max particle size = 30 mm, round to sub-rounded, poorly graded, no odour, moist, homogeneous, roots and rootlets, gravel has orange brown stains [FILL or COLLUVIUM]</p> | |
| 1.0 | <p>0.65 m: EOH - Refusal on cobbles. Two holes attempted. No groundwater encountered</p> | | 1.0 | <p>0.45 m: EOH - Refusal fo auger on tree root. Hole is collapsing. No groundwater encountered</p> | |
| 1.5 | | | 1.5 | | |
| 2.0 | | | 2.0 | | |
| 2.5 | | | 2.5 | | |
| 3.0 | | | 3.0 | | |

BGC05-2480HAY-AH01

| | |
|------------------------------------|--|
| SITE OBSERVATION FORM: | DNV Landslide Risk Assessment |
| LOCATION: | 2486 Hayseed Close |
| INSPECTION DATE: (mm/dd/yy) | 10/27/05 |
| WEATHER: | Sunny, rained previous few days |



BGC ENGINEERING INC.
AN APPLIED EARTH SCIENCES COMPANY

500 - 1045 Howe Street
Vancouver, BC
Canada V6Z 2A9


| THICKNESS OF LOOSE MATERIALS | <1 m | 1-2 m | 2-3 m | >3 m |
|---------------------------------|------|-------------------------------------|-------|------|
| FENCE LINE | | <input checked="" type="checkbox"/> | | |
| 10 m DOWNSLOPE FROM SLOPE CREST | | <input checked="" type="checkbox"/> | | |

| | | | |
|--|--------------------|---------------|-------------------------------------|
| SLOPE BELOW FENCE/ RETAINING STRUCTURE | SLOPE = 36° | | |
| | CRACKS | SLIDES | EROSION |
| | | | <input checked="" type="checkbox"/> |
| OBSERVATIONS: Some erosion directly below retaining structure | | | |

| | | | |
|---|-------------------------------------|--------------------|----------------|
| TREES BELOW FENCE/ RETAINING STRUCTURE | STRAIGHT | PISTOL-BUTT | LEANING |
| PERCENT CONIFER: | <input checked="" type="checkbox"/> | | |
| 90% | | | |
| OBSERVATIONS: | | | |

| | | | |
|--|--|-------------------------------------|-------------------------------------|
| RETAINING STRUCTURES | YES <input checked="" type="checkbox"/> | NO | HEIGHT= 2.0 m |
| TYPE | CONCRETE | TIMBER CRIB | OTHER: Stacked logs |
| | | | <input checked="" type="checkbox"/> |
| DEFORMATION | UNDEFORMED | CRACKED | BULGING |
| | | <input checked="" type="checkbox"/> | |
| OBSERVATIONS: Stacked log wall is rotting. Layers of slumping bricks. | | | |

| | | |
|---|--|-----------|
| DEFORMATION IN BACKYARD | YES <input checked="" type="checkbox"/> | NO |
| LOCATION: | | |
| DESCRIPTION: Settling in backyard at top of retaining structure. | | |



| | | |
|---------------------------|------------|---|
| POOLS | YES | NO <input checked="" type="checkbox"/> |
| DESCRIPTION: None. | | |

| | | |
|--|------------|---|
| SEEPAGE/ SPRINGS IN OR BELOW FILL | YES | NO <input checked="" type="checkbox"/> |
| OBSERVATIONS: None observed. | | |

HOUSE DISTANCE TO CREST = 6.6 m

| | | | | | |
|---|-------------------------------------|-------------------------------------|------------------|-------------------|---------------|
| RECEIVES SURFACE RUNOFF FROM | BACKYARD | ½ ROOF | FULL ROOF | FRONT YARD | STREET |
| | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | | | |
| OBSERVATIONS: Backyard downspout drips directly onto lawn. | | | | | |

| | | | |
|---|------------|---|---------------|
| CONNECTED TO STORM SEWER | YES | NO <input checked="" type="checkbox"/> | UNSURE |
| OWNERS COMMENTS: DNV reports that this property is not connected to the storm sewer. | | | |

| |
|---|
| GENERAL OBSERVATIONS |
| <ul style="list-style-type: none"> Owner noted slight slumping of soil behind wood/brick retaining wall on east side of backyard within last couple of days Owner notes that 3 trees on west side of backyard fell 10 years ago during a heavy storm Bricks/ logs and pieces of asphalt lying on slope |



Figure 1. 2486 Hayseed Close – Front of the house



Figure 2. 2486 Hayseed Close – View looking south towards a slumping brick retaining wall



Figure 3. 2486 Hayseed Close – Top view of settling brick retaining wall



Figure 4. 2486 Hayseed Close – View down-slope on north side of property where 3 trees fell during a heavy storm 10 years ago

INSPECTION LOCATION # 2486 Hayseed

Project : DNV Landslide Risk Assessment

Project No. : 0404-002-01

Location : 2486 Hayseed
Drill Method : Dutch Hand Auger
Inspection Date : 27 Oct 05
Logged by : MB/ES
Reviewed by : MJP

| Depth (m) | Lithologic Description | Depth To Water Table | Depth (m) | Lithologic Description | Depth To Water Table |
|-----------|--|----------------------|-----------|---|----------------------|
| | <p>AUGERHOLE: BGC05-2486HAY-AH01 6.1 m Back from Crest FINAL DEPTH OF AUGERHOLE: 1.20 m THICKNESS OF LOOSE MATERIALS: 1.00 m</p> | | | <p>AUGERHOLE: BGC05-2486HAY-AH02 10 m Downslope FINAL DEPTH OF AUGERHOLE: 1.10 m THICKNESS OF LOOSE MATERIALS: 1.10 m minimum</p> | |
| 0.0 | <p>SAND (SM) Silty, trace fine gravel, poorly graded, loose, max particle size = 2 mm, sub-rounded, dark brown, no odour, moist, homogeneous, no cementation [TOPSOIL]</p> | | 0.0 | <p>SAND (SM) Silty, trace fine gravel, poorly graded, loose, dark brown, no odour, moist, homogeneous, no cementation [TOPSOIL]</p> | |
| 0.5 | <p>SAND (SM) Silty, trace fine to coarse gravel, poorly graded, loose, some gravel sized fine sand clasts, maximum particle size = 15 mm, sub-rounded, brown, no odour, moist, homogeneous, no cementation [FILL]</p> | | 0.5 | <p>SAND (SM) Fine to medium sand, silty, some fine to medium gravel, some gravel sized silt clasts, poorly graded, loose, max particle size = 60 mm, brown, no odour, moist, homogeneous, no cementation [FILL]</p> | |
| 1.0 | <p>SAND (SM) Fine to medium sand, some silt, some gravel sized fine sand clasts, poorly graded, loose, sub-rounded, light brown to grey, no odour, moist, homogeneous, no cementation, some orange mottling [FILL] 0.80 m: Some gravel noted SILT (ML) and SAND (SP) Fine sand, gravel sized silt and fine sand clasts, low plastic, stiff, grey and brown, no odour, moist, homogeneous, no cementation, no dilatancy, trace roots [Weathered GLACIOMARINE]</p> | | 1.0 | <p>0.60 m: Charcoal clasts</p> | |
| 1.5 | <p>1.20 m: EOH - Refusal as material is too stiff to auger through. Four holes attempted. No groundwater encountered</p> | | 1.5 | <p>1.10 m: EOH - Refusal on gravels. Two holes attempted downslope. No groundwater encountered</p> | |
| 2.0 | | | 2.0 | | |
| 2.5 | | | 2.5 | | |
| 3.0 | | | 3.0 | | |

BGC05-2486HAY-AH01