




LEGEND

- BGC Hand Auger Holes**
- ⊕ (See Appendix 1 for Logs)
- Previous Landslides**
- 1999
- 2005 Cracks
- 1980 Cracks
- 5m Contours
- × Properties not connected to storm sewer (or unknown) as of December 2005



NOTES:
 1. TOPOGRAPHY PROVIDED BY DNV ON OCTOBER 18th 2005.
 2. THIS DRAWING ACCOMPANIES A BGC ENGINEERING INC. REPORT TO DISTRICT OF NORTH VANCOUVER TITLED "BERKELEY LANDSLIDE RISK MANAGEMENT, PHASE 1: RISK ASSESSMENT" DATED JANUARY 2006. THIS DRAWING MUST NOT BE USED WITHOUT CONSIDERATION OF THE STATEMENT OF LIMITATION GIVEN IN THE TEXT OF THE ACCOMPANYING REPORT.



SCALE	1:2,000
DATE	JAN 2006
DESIGNED	WVL
DRAWN	MLP
CHECKED	MLP
APPROVED	MLP

BGC ENGINEERING INC.
 AN APPLIED EARTH SCIENCES COMPANY

PROJECT: BERKELEY LANDSLIDE RISK MANAGEMENT
 TITLE: TOPOGRAPHIC BASE MAP AND LOCATION OF PREVIOUS LANDSLIDES
 PROJECT NO.: 0404-002
 DATE: 1